

October 2011 Inspection Report Claremont Tower Clock

LOCAL NAME & CONTACT INFO

Calburt Johnson 385 8109

Lindin 363 2746

Report by:

Philip Martin

Jamaica.heritage@yahoo.com

Osborn Store, Clarendon

Location at town center Claremont, St Ann. N18.33175° W -077.17613.
This clock works and tells the correct time. The bell chime does not function. About 9 foot 5 inches square at base, about 30 feet high.

General Conditions

- 1) General conditions unknown until inspection is preformed.
- 2) In operating condition for several years, general condition good.

Suggested Actions for Health and Safety:

- 1) Un known until full inspection.
- 2) Repair Roof
- 3) Repair lightning rod system.
- 4) Needs exterior painting.

